

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 06/27/2016 02:15 PM		4. Date/Time of Death 06/27/2016 03:20 PM		5. Fatal Case No 9		
6. Mine Information :										
a) Mining Company Name Atlas Quarries			b) Mine Name Atlas Qu Pt Crusher #1			c) Parent of Mining Company Atlas Asphalt; White River Bituminous				
7. Mine Location :		a) City Cord		b) County Independence		c) State AR		8. Mine ID Number: 03-01720		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees: 12		a) Total	b) Underground	c) Open Pit/Quarry 6		d) Mill/Prep Plant 5	e) Other 1
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees:			b) Contractor Employees:		a) Mine Employees:			b) Contractor Employees:		
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches	90			
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries:		22. Fatal Injuries: 1								
23. Victim Information :				a) Name Billy Cude		b) Age 61				
c) Regular Job Title: Superintendent			d) Activity at Time of Accident: Truck driver			<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:	24	b) at the mine:	24	c) at activity (23d)	24	d) with Contractor				
25. Autopsy Performed: If Yes, Location YES Little Rock, AR						26. Mine Telephone No.: (870) 932-1246				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
A Caterpillar D250E haul truck was positioning to dump a load of material near the edge of a highwall in order to build a ramp to the lower bench. The loaded haul truck rolled backwards over the 90 foot highwall.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: D250E		
30. District: M5000 South Central		32. Field Office: Little Rock AR			33. Event Number: 6735914
34. Accident Investigator: Robert Seelke			35. MSHA Person Notified: Nick Gutierrez		Date 06/27/2016
					Time 02:30 PM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: David Weaver			Date 06/28/2016
38. Reason For Amendment:					