PR001
16-Jan-15

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Powered Haulage	12/29/2014 03:02 PM	12/29/2014 03:45 PM	24

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Zeotech Corporation	Tilden Plant	O Paul Leonard Jr

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Tilden	Mcmullen	TX	41-03374	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
COMMON CLAYS MINING, N.E.C.	18		2	12	4

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident:		18. Number of Persons Unaccounted For:	
a) Mine Employees: 17	b) Contractor Employees:	a) Mine Employees:	b) Contractor Employees:

19) Location of Accident

- [ ] 01-Underground
- [x] 03-Open Pit
- [ ] 07-Advance Mining
- [ ] 30-Mill/Prep Plant
- [ ] Other (specify)
- [ ] 02-Surface at Underground
- [ ] 06-Dredge Mining
- [ ] 08-Retreat Mining
- [ ] 99-Office Facility

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
	1

23. Victim Information : a) Name	b) Age
Adrian A. Moreno	21

c) Regular Job Title:	d) Activity at Time of Accident:	[x] Mine Employee
Warehouse Bagger	Operating Forklift	

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	0	1	0	b) at the mine:	0	1	0	c) at activity (23d)	0	0	1	d) with Contractor			

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
YES		(361) 274-3357

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating a forklift, hauling a bag of dust, when the forklift overturned.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
Caterpillar	2P5000

30. District:	32. Field Office:	33. Event Number:
M5000 South Central	San Antonio TX	6658805

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Wesley L. Hackworth	Elwood Burriss	12/29/2014	04:11 P

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Amended	Mike Hancher MH	01/02/2015

38. Reason For Amendment:

Item #23 (c)