

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 08/03/2015 02:45 PM		4. Date/Time of Death 08/03/2015 03:00 PM		5. Fatal Case No 13	
6. Mine Information :									
a) Mining Company Name Pinky's Aggregates Inc			b) Mine Name Pinky's Aggregates Inc			c) Parent of Mining Company Dale Honsey			
7. Mine Location :									
a) City Rolette		b) County Rolette		c) State ND		8. Mine ID Number: 32-00909		9. Union: NO	
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		11. Number of Mine Employees:		11. Number of Mine Employees:		11. Number of Mine Employees:
			a) Total 6	b) Underground 0	c) Open Pit/Quarry 6	d) Mill/Prep Plant 0	e) Other 0		
12. Contractor Name:						13. Union		14. Contractor ID Number:	
15. Contractor Address:									
a) City		b) County			c) State		d) Zip Code		
16. Number of Contractor Employees:									
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:				
a) Mine Employees: 6		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0		
19) Location of Accident								20. Mining Height:	
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)	
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet	Inches
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1							
23. Victim Information :									
a) Name William Makela					b) Age 64				
c) Regular Job Title: Loader Operator				d) Activity at Time of Accident: Loading Trucks				<input checked="" type="checkbox"/> Mine Employee	
24. Experience :									
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days
a) Total: 0 44 0			b) at the mine: 0 14 0			c) at activity (23d) 0 14 0			d) with Contractor 0 0 0
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.: (701) 246-3880			

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was operating a frontend loader, loading trucks from a stockpile, when he exited the loader. While outside the loader, the stockpile sloughed burying the victim between the stockpile and the loader.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Deere & Co.				29. Model: 724J					
30. District: M6000 Rocky Mountain		32. Field Office: Rapid City SD				33. Event Number: 6696940			
34. Accident Investigator: Leon Mueller				35. MSHA Person Notified: Pete Del Duca		Date 08/03/2015		Time 03:15 PM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Pete Del Duca				Date 08/04/2015			
38. Reason For Amendment:									