



Legend

No Reading: Reading Beyond The Capability Of The Instrument

Circled Number: Test Equipment Indicated Reading Is Not Reliable

Measurements Taken With N.G.I. Resistance Tester Using 4 Pole Method With Pins Installed At 0'-20'-40'-60' Intervals
Measurements Taken From End of Track To Inby Seal Installed In That Area

Measurements Taken With N.G.I. Resistance Tester Using 4 Pole Method With Pins Installed At 0'-20'-40'-60' Intervals
Measurements Taken From No. 4 Belt Tailpiece To Inby Seal Installed In That Entry

Measurements Taken With N.G.I. Resistance Tester 4 Pole Method—Readings Are In Ohms
Measurements Taken From End Of Track To SS4010: Top and Floor Readings.

Measurements Taken With 2-No. 12 Solid Copper Wires In Parallel
Measurements Taken From No. 6 Belt Starter And No. 4 Belt Tailpiece

Measurements Taken With N.G.I. Resistance Tester Using 4 Pole Method
Measurements Taken From End Of Track To Where Seals Were Installed

Appendix KK

Sago Mine, MSHA ID 46-08791 Wolf Run Mining Company

Earth Resistance Measurement Values

