

7

July 8 - Aug 6

✓

Main

West

**PRE-SHIFT  
SECTIONS**

# PRE-SHIFT SECTIONS.

DATE OF EXAMINATION 7-8-07

SECTION/AREA Main West

TIME OF EXAMINATION START 1120 AM/PM

END 1:50 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 157 AM/PM

CALLED OUT BY Josh Fielder

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8			33450		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None Observed	
#1 ENTRY	20.8	0	0			None Observed	
#2 ENTRY	20.8	0	0			None Observed	
#3 ENRTY	20.8	0	0			None Observed	
#4 ENTRY	20.8	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
last open	accumulations	Pushed & dusted

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature**

CERT. # 9174

COUNTER SIGNATURE **Signature**

CERT. # 8462

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-8-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 706 AM/PM END 845 AM/PM  
 EXAM. CALLED OUT YES/NO CALL OUT TIME 9:55 AM/PM  
 CALLED OUT BY Bryan Kimber REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	26.9	0	0	43056		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY	26.9	0	0			None observed	
#2 ENTRY	20.9	0	0			None observed	
#3 ENRTY	20.9	0	0			None observed	
#4 ENTRY	20.9	0	0			Coal HCC.	Cleaned
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 7658  
 COUNTER SIGNATURE **Signature** CERT.# 8925  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/9/07

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START '312 AM/PM

END 421 AM/PM

EXAM. CALLED OUT — YES/NO (NO)

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	43,452		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS	20.9	0	0			NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
FEEDER	ACCUMULATIONS	CLEANED
#2 ENTRY	LOOSE RES	SCALED DOWN

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT  
TIME OF EXAM

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ **Signature** \_\_\_\_\_ CERT.# 9658  
 COUNTER SIGNATURE \_\_\_\_\_ **Signature** \_\_\_\_\_ CERT.# 03892  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 9 07

SECTION/AREA Main West

TIME OF EXAMINATION START 11 ~~AM~~/PM

END 1246 AM/~~PM~~

EXAM. CALLED OUT ~~YES~~/NO

CALL OUT TIME 1257 AM/~~PM~~

CALLED OUT BY Benny Alfred

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	39340		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans Charger	20.9	0	0	α		None observed	

V= VIOLATION  
H= HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#1 entry	life line down	Hung Back up

PRE-SHIFT REMARKS All work areas + travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

COUNTER SIGNATURE \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

CERT.# 9279

CERT.# 03892

2MSHA02754

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-9-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:42 AM/PM

END 8:31 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	<del>0</del>	40,050		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
TRANS-CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7488

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-10-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 3:10  AM  PM

END 4:10  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 5:15  AM  PM

CALLED OUT BY CHARLES WHITTEN

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	39572		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY	20.9	0	0			NONE OBSERVED	
#2 ENTRY	20.9	0	0			NONE OBSERVED	
#3 ENRTY	20.9	0	0			NONE OBSERVED	
#4 ENTRY	20.9	0	0			NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS-CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7999

COUNTER SIGNATURE

Signature

CERT. # 05892

SECTION SUPERVISOR

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-10-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 11:00 AM/PM END 12:30 AM/PM  
 EXAM. CALLED OUT — YES/NO CALL OUT TIME 12:45 AM/PM  
 CALLED OUT BY Benny Alfred REPORT RECEIVED BY **Signature**  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	41,020		None obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None obs.	
#1 ENTRY	20.9	0	0			None obs.	
#2 ENTRY	20.9	0	0			None obs.	
#3 ENRTY	20.9	0	0			None obs.	
#4 ENTRY	20.9	0	0			None obs.	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0			None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#1 entry	Trash	clean up

PRE-SHIFT REMARKS Areas Reported safe AT Time of EXAM

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 9279  
 COUNTER SIGNATURE **Signature** CERT.# 05892  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-10-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:55 AM/PM (P)

END 9:11 AM/PM (P)

EXAM. CALLED OUT (YES)/NO

CALL OUT TIME 9:45 AM/PM (P)

CALLED OUT BY Dave Black

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31144		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#2 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#3 ENRTY	20.9	0	0	OK		NONE OBSERVED	
#4 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS/CHARGERS	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
LOX-CWY	ACCUMULATIONS	CLEANED & DUSTED

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME  
OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

**Signature**

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-11-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 3:55  AM  PM

END 5:00  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 5:10  AM  PM

CALLED OUT BY Dave Black

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38620		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#2 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#3 ENRTY	20.9	0	0	OK		NONE OBSERVED	
#4 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS-CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
FEEDER	ACCUMULATIONS IN WALKWAY	CLEARED

PRE-SHIFT REMARKS SECTION REPORTED REASONABLY SAFE TO WORK AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 11 07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 1102 AM/PM END 1207 AM/PM  
 EXAM. CALLED OUT YES/NO CALL OUT TIME 114 AM/PM  
 CALLED OUT BY Don Erickson REPORT RECEIVED BY Signature  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	33586		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY	20.9	0	0	α		None observed	
#2 ENTRY	20.9	0	0	α		None observed	
#3 ENRTY	20.9	0	0	α		None observed	
#4 ENTRY	20.9	0	0	α		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Charger	20.9	0	0	α		None observed	

V= VIOLATION  
 H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
F.B.	Accumulations	Cleaned

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE Signature CERT.# 9207  
 COUNTER SIGNATURE \_\_\_\_\_ CERT.# 02993  
 SECTION SUPERVISOR \_\_\_\_\_  
INITIALS (NOT REQUIRED) 10 2MSHA02760

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-11-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START ~~8:03~~ 8:03 AM/PM

END 9:26 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	43325		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#2 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#3 ENRTY	20.9	0	0	OK		NONE OBSERVED	
#4 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS / CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-12-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 3:35  AM  PM

END 4:44  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 5:15  AM  PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	40,712		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#2 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#3 ENRTY	20.9	0	0	OK		NONE OBSERVED	
#4 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS-CHARGER	20.9	0	0	OK		NONE OBSERVED	

V= VIOLATION  
H= HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME  
OF EXAMINATION

PRE-SHIFT/MINE EXAMINEE

Signature

CERT.# 7485

COUNTER SIGNATURE

Signature

CERT.# 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/20/07

SECTION/AREA Main West

TIME OF EXAMINATION START 11  AM  PM

END 1244  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 116  AM  PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	41230		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	0		None observed	
#1 ENTRY	20.9	0	0	0		None observed	
#2 ENTRY	20.9	0	0	0		None observed	
#3 ENRTY	20.9	0	0	0		None observed	
#4 ENTRY	20.9	0	0	0		None observed	
#5 ENTRY							
#6 ENTRY							
Trans/Chargers	20.9	0	0	0		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
EB.	accumulations	Cleaned
Trans	Trash accum.	Cleaned
#3 entry	Need Dust	shut down and dusted

PRE-SHIFT REMARKS All area appeared safe at  
Time of exam

PRE-SHIFT/MINE EXAMINER Signature

CERT.# 9278

COUNTER SIGNATURE Signature

CERT.# 03892

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-12-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:50 AM/PM

END 9:21 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	36,127		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#2 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#3 ENRTY	20.9	0	0	OK		NONE OBSERVED	
#4 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS-CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-13-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 333 AM/PM

END 410 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 5:07 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	40328		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#2 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#3 ENRTY	20.9	0	0	OK		NONE OBSERVED	
#4 ENTRY	20.9	0	0	OK		NONE OBSERVED	
#5 ENTRY							
#6 ENTRY							
TRANS. CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7999

COUNTER SIGNATURE

Signature

CERT. # 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-13-07

SECTION/AREA Main West

TIME OF EXAMINATION START 12:00 AM/PM

END 1:20 AM/PM

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME 1:57 AM/PM

CALLED OUT BY Josh Fielder

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	31200		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	G		None Observed	
#1 ENTRY	20.9	0	0	OK		None Observed	
#2 ENTRY	20.9	0	0	OK		None Observed	
#3 ENRTY	20.9	0	0	OK		None Observed	
#4 ENTRY	20.9	0	0	OK		None Observed	
#5 ENTRY							
#6 ENTRY							
Trans/Chargers	20.9	0	0	OK		None Observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
LOX	BLACK	ducted
COX	ACC	pushed

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of Exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT.# 9174

COUNTER SIGNATURE Signature

CERT.# 8762

SECTION SUPERVISOR

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-13-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 701 AM/PM AM END 820 AM/PM AM  
 EXAM. CALLED OUT —  YES /  NO CALL OUT TIME 832 AM/PM AM  
 CALLED OUT BY Brandon Kimber REPORT RECEIVED BY Signature  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	33,256		no obs	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			no obs	
#1 ENTRY	20.9	0	0			no obs	
#2 ENTRY	20.9	0	0			no obs	
#3 ENRTY	20.9	0	0			no obs	
#4 ENTRY	20.9	0	0			no obs	
#5 ENTRY							
#6 ENTRY							
TRANS/charges	20.9	0	0			no obs	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas Appr'd Sep at the of exam

PRE-SHIFT/MINE EXAMINER Signature CERT.# 9658  
 COUNTER SIGNATURE Signature CERT.# 4735  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/14/07

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 300 AM/PM

END 412 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	32,990		None OBS.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None OBS	
#1 ENTRY	20.9	0	0			None OBS.	
#2 ENTRY	20.9	0	0			None OBS.	
#3 ENRTY	20.9	0	0			1-10 STEEL FOUND STEEL	
#4 ENTRY	20.9	0	0			None OBS.	
#5 ENTRY							
#6 ENTRY							
TRAWS	20.9	0	0			None OBS.	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPROPRIATE SAMPLED  
AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ **Signature** \_\_\_\_\_ CERT.# 9658  
 COUNTER SIGNATURE \_\_\_\_\_ **Signature** \_\_\_\_\_ CERT.# 8462  
 SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 2-14-07  
 TIME OF EXAMINATION START 11:50  AM /  PM  
 EXAM. CALLED OUT YES /  NO  
 CALLED OUT BY Josh Fielder

SECTION/AREA Main West  
 END 1:15 AM /  PM  
 CALL OUT TIME 1:35 AM /  PM  
 REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	34360		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None Observed	
#1 ENTRY	20.8	0	0			None Observed	
#2 ENTRY	20.8	0	0			None Observed	
#3 ENRTY	20.8	0	0			None Observed	
#4 ENTRY	20.8	0	0			None Observed	
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
 H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9174  
 COUNTER SIGNATURE **Signature** CERT. # 4735  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-14-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 706 AM/PM (AM) END 831 AM/PM (AM)  
 EXAM. CALLED OUT (YES)/NO CALL OUT TIME 9:30 AM/PM (AM)  
 CALLED OUT BY Brandon Kimbu REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	34462		none obs	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none obs	
#1 ENTRY	20.9	0	0			none obs	
#2 ENTRY	20.9	0	0			none obs	
#3 ENRTY	20.9	0	0			none obs	
#4 ENTRY	20.9	0	0			none obs	
#5 ENTRY							
#6 ENTRY							
Transfer charge	20.9	0	0			none obs	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9658  
 COUNTER SIGNATURE Signature CERT. # 8462  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/15/07

SECTION/AREA WEST MAINS

TIME OF EXAMINATION START 310 AM/PM

END 439 AM/PM

EXAM. CALLED OUT — YES/NO NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	33,960		NONE OBS.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBS.	
#1 ENTRY	20.9	0	0			NONE OBS.	
#2 ENTRY	20.9	0	0			NONE OBS.	
#3 ENRTY	20.9	0	0			NONE OBS.	
#4 ENTRY	20.9	0	0			NONE OBS.	
#5 ENTRY							
#6 ENTRY							
TRANS	20.9	0	0			NONE OBS.	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT  
TIME OF EXAM

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9658

COUNTER SIGNATURE

Signature

CERT. # 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 2-15-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:30  AM  PM

END 1:02  AM  PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 1:10  AM  PM

CALLED OUT BY Josh Fielder

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	44320		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	0		None Observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0	0		None Observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Lox	Black	dusted

PRE-SHIFT REMARKS all areas safe @ time of exam.

PRE-SHIFT/MINE EXAMINER **Signature**

CERT.# 9174

COUNTER SIGNATURE **Signature**

CERT.# 4735

SECTION SUPERVISOR **Signature**

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 2-15-07

SECTION/AREA Main West

TIME OF EXAMINATION START 704 AM/PM

END 824 AM/PM

EXAM. CALLED OUT — YES/NO (Circled)

CALL OUT TIME 955 AM/PM

CALLED OUT BY Brandon Kemper

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	21	0	0	45600		none obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	0		none obs.	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
<u>Puller line</u>	21	0	0	0		none obs.	
<u>Transformer</u>	21	0	0	0		none obs.	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 9658  
 COUNTER SIGNATURE **Signature** CERT.# 4935  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-16-07

SECTION/AREA WEST MAIN

TIME OF EXAMINATION START 300 ~~AM~~/PM

END 414 ~~AM~~/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	44,850		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PELLAR LINE	20.9	0	0			NONE OBSERVED	
TRANSFORMER	20.9	0	0			NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS ALL AREAS APPEARED SAFE AT TIME  
OF EXAM

PRE-SHIFT/MINE EXAMINER

Signature  
**Signature**

CERT.# 9658

COUNTER SIGNATURE

CERT.# 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-16-07  
 TIME OF EXAMINATION START 1101  AM /  PM  
 EXAM. CALLED OUT —  YES /  NO  
 CALLED OUT BY Don Erickson

SECTION/AREA Main West  
 END 1232  AM /  PM  
 CALL OUT TIME 1248  AM /  PM  
 REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	53320		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None observed	
#1 ENTRY	20.9	0	0	OK		None observed	
#2 ENTRY	20.9	0	0	OK		None observed	
#3 ENRTY	20.9	0	0	OK		None observed	
#4 ENTRY	20.9	0	0	OK		None observed	
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	OK		None observed	
Trans/Charger	20.9	0	0	OK		None observed	

V = VIOLATION  
 H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
TAIL Gate	Acc.	CLEANED

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature**  
 COUNTER SIGNATURE \_\_\_\_\_  
 SECTION SUPERVISOR \_\_\_\_\_

CERT. # 2207  
 CERT. # 03892

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-16-07

SECTION/AREA M. West

TIME OF EXAMINATION START 7:00 AM/PM

END 7:55 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 8:35 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	42626		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PULLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS/KWARGCK	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER **Signature**  
COUNTER SIGNATURE **Signature**  
SECTION SUPERVISOR **Signature**

CERT. # 7483  
CERT. # 7485

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-17-07

SECTION/AREA M. WEST

TIME OF EXAMINATION START 3:05  AM  PM

END 4:30  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 545  AM  PM

CALLED OUT BY DALE BLACK REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	44010		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS / CHARGE	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AGENTS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 17 07

SECTION/AREA Main West

TIME OF EXAMINATION START 1201 AM/PM ~~AM~~

END 120 AM/PM ~~PM~~

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME 137 AM/PM ~~PM~~

CALLED OUT BY Benny Allred

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51376		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	α		None observed	
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
No intake	water	pumped
#7 Belt	accumulation	clean and shooled

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at the time of this exam.

PRE-SHIFT/MINE EXAMINER

**Signature**

CERT. # 9279

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-17-07

SECTION/AREA M. WEST

TIME OF EXAMINATION START 7:00 AM/PM

END 8:10 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	41850		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS/CHARGER	20.9	0	0	OK		NONE OBSERVED	

V= VIOLATION  
H= HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
D-BOX FOR SLC	NO FIRE EXTINGUISHER	REPLACED FIRE EXTINGUISHER

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

**Signature**

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7483

SECTION SUPERVISOR

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-18-07  
 TIME OF EXAMINATION START 305 (AM/PM)  
 EXAM. CALLED OUT — (YES/NO)  
 CALLED OUT BY Dale Black

SECTION/AREA Main west  
 END 400 (AM/PM)  
 CALL OUT TIME 5:12 (AM/PM)  
 REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	45,530		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	OK		None observed	
Trans/charger	20.9	0	0	OK		None observed	

V= VIOLATION  
 H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Feeder	Accumulation	Cleaned

Sent people to install door. CA 71807

PRE-SHIFT REMARKS Need a man door installed at 145 on return stopping. Section appeared safe for work and travel at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 7483  
 COUNTER SIGNATURE \_\_\_\_\_ CERT.# 03892  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7.18.07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:41  AM /  PM

END 1:06  AM /  PM

EXAM. CALLED OUT —  YES /  NO

CALL OUT TIME 1:12  AM /  PM

CALLED OUT BY Benny AlRed

REPORT RECEIVED BY

**Signature**

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51832		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0			None observed	
Trans/Charger	20.9	0	0			None observed	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Return	No door at 145	Installed door
#3 entry	Needed dusted	shut down and dusted

PRE-SHIFT REMARKS Areas Reported Reasonably safe at time of examination

PRE-SHIFT/MINE EXAMINER

**Signature**

CERT.# 9279

COUNTER SIGNATURE

CERT.# 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

31

2MSHA02781

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-18-07

SECTION/AREA M. West

TIME OF EXAMINATION START 7 00 AM/PM

END 7 51 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:55 AM/PM

CALLED OUT BY DAVE BLACK REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	49985		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS/CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature

COUNTER SIGNATURE \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

CERT. # 7483

CERT. # 7485

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-19-07

SECTION/AREA W. West

TIME OF EXAMINATION START 300 AM/PM

END 421 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	ok	50,050		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	ok	out by		None	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	ok			None observed	
Truss	20.9	0	ok			None observed	

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#3	Bad ribs	Took down with CM

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 19 07

SECTION/AREA Main West

TIME OF EXAMINATION START 1103  AM  PM

END 1216  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 1233  AM  PM

CALLED OUT BY Don Erickson

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	53144		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	α		None observed	
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#3 entry	2 stoppings damaged	Repaired

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

COUNTER SIGNATURE \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

CERT. # 9207

CERT. # 03892

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-19-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 703 AM/PM

END 752 AM/PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 855-955 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	52,675		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS/CITARGE	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7482

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-20-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 319  AM  PM

END 428  AM  PM

EXAM. CALLED OUT —  YES  NO

CALL OUT TIME 520  AM  PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50,880		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS/CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER  
COUNTER SIGNATURE  
SECTION SUPERVISOR

Signature

CERT.# 7483

CERT.# 4135

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-20-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:09 AM/PM AM

END 12:16 AM/PM PM

EXAM. CALLED OUT (YES)/NO

CALL OUT TIME 12:30 AM/PM PM

CALLED OUT BY Brandon Kimber REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	50344		none obs	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none obs	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
<i>pellean line</i>	20.9	0	0			None obs	
<i>trans-changers</i>	20.9	0	0			None obs	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of  
EXAM

PRE-SHIFT/MINE EXAMINER Signature

CERT. # 9658

COUNTER SIGNATURE Signature

CERT. # 4735

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-20-07

SECTION/AREA Main West

TIME OF EXAMINATION START 7:30 AM/PM

END 8:15 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY J Fielder

REPORT RECEIVED BY **Signature**

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	49454		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		none observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillage Line	20.9	0	0	OK		none observed	
TRANS / charger	20.9	0	0	OK		none observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

**PRE-SHIFT REMARKS**

Areas appeared reasonably safe  
AT Time of pre-shift

PRE-SHIFT/MINE EXAMINER

**Signature**

CERT. # 9174

COUNTER SIGNATURE

CERT. # 4735

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/21/07  
 TIME OF EXAMINATION START 3:10  AM/PM  
 EXAM. CALLED OUT — YES  NO  
 CALLED OUT BY \_\_\_\_\_

SECTION/AREA Main West  
 END 445  AM/PM  
 CALL OUT TIME \_\_\_\_\_ AM/PM  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	50,126		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			none ob	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0%	0			none ob	
Transformer	20.8	0%	0			none ob	
Stopping line	20.8	0%	0			stoppings knocked out.	working on.

V = VIOLATION  
 H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas except stopping line safe @ time of exam

PRE-SHIFT/MINE EXAMINER **Signature** \_\_\_\_\_ CERT. # 9179  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4785  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-21-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:24  AM  PM

END 12:20  AM  PM

EXAM. CALLED OUT —  YES  NO

CALL OUT TIME 2:20  AM  PM

CALLED OUT BY Brandon Kimber

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	5/120		none obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none obs.	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar Line	20.9	0	0			none obs.	
Turnover/charger	20.9	0	0			none obs.	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre shift.

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9658  
 COUNTER SIGNATURE **Signature** CERT. # 4135  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-21-07

SECTION/AREA MAINWAY

TIME OF EXAMINATION START 8:00 AM/PM

END 9:00 AM/PM

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY J Fielden

REPORT RECEIVED BY Signature

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	49,900		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	OK		4 stoppings Blown out	stopping wires Repaired 7-21-07
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
P. 1122 Line	20.8	0	0	OK		none observed	
TRANSFORMER	20.8	0	0	OK		none observed	
Ch Began	20.8	0	0	OK		none observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas Appeared Reasonably safe  
AT time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT.# 9174  
 COUNTER SIGNATURE Signature CERT.# 4135  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/22/07 SECTION/AREA Marsh West  
 TIME OF EXAMINATION START 4:05 AM/PM END 5:10 AM/PM  
 EXAM. CALLED OUT — YES/NO NO CALL OUT TIME \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20 <sup>-8</sup>	8%	0	50, 100		none ok	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20 <sup>-8</sup>	6%	0			none ok	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20 <sup>-8</sup>	9%	0			none ok	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all ones safe @ time of exam

PRE-SHIFT/MINE EXAMINEE **Signature** CERT.# 9174  
 COUNTER SIGNATURE \_\_\_\_\_ CERT.# 4735  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-22-07

SECTION/AREA Main West

TIME OF EXAMINATION START 1100 AM/PM

END 1204 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1-35 AM/PM

CALLED OUT BY R. Johnson

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	49400		none obs.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none obs.	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pittas line	20.9	0	0			none obs.	
Transformer	20.9	0	0			none obs.	

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
FERRAR	ACCUM	CLEARING
TRAINS	TRASH	CLEARING

PRE-SHIFT REMARKS All areas safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT.# 9658

COUNTER SIGNATURE Signature

CERT.# 4735

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-22-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 7:00 AM/PM AM

END 9:30 AM/PM AM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 9:40 AM/PM AM

CALLED OUT BY J Fielder

REPORT RECEIVED BY Signature  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	48800		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	OK		none observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar Line	20.8	0	0	OK		none observed	
Towers for men	20.8	0	0	OK		none observed	
charger	20.8	0	0	OK		none observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS

AREAS APPEARED REASONABLY ETC AT  
Time of pre shift

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 9174

COUNTER SIGNATURE

Signature

CERT.# 8462

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/23/07

SECTION/AREA Main West

TIME OF EXAMINATION START 330 AM/PM

END 515 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	50725		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			none observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0%	0			none observed	
Transformer	20.8	0%	0			none observed	
Charger	20.8	0%	0			none observed	

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Pillar line	Black	dusted
Feeder	Acc.	cleaned

PRE-SHIFT REMARKS all area safe @ time of  
start

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9174  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735  
 SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-23-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 11:03  AM/PM END 12:41  AM/PM  
 EXAM. CALLED OUT —  YES/NO CALL OUT TIME 2:00  AM/PM  
 CALLED OUT BY Brandon Kimber REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	49800		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE	9						
RETURN	20.9	0	0			None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar Line	20.9	0	0			None observed	
Turnstiles	20.9	0	0			None observed	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Return	Life Line Down	Rehung

PRE-SHIFT REMARKS Area appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9658  
 COUNTER SIGNATURE Signature CERT. # 8462  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-23-07

SECTION/AREA Main West

TIME OF EXAMINATION START 7:30 AM/PM

END 9:30 AM/PM

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME 9:54 AM/PM

CALLED OUT BY Josh Fielder

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	49272		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	Q		None Observed	
#1 ENTRY	20.8	0	0	Q		None Observed	
#2 ENTRY	20.8	0	0	Q		None Observed	
#3 ENRTY	20.8	0	0	Q		None Observed	
#4 ENTRY	20.8	0	0	Q			
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-23-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 7:30 AM/PM END 9:30 AM/PM  
 EXAM. CALLED OUT — YES/NO CALL OUT TIME 9:54 AM/PM  
 CALLED OUT BY Josh Fielder REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	49272		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None Observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0			None Observed	
transformer	20.8	0	0			None Observed	

V= VIOLATION  
H= HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Feeder	Acc	cleared

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9174  
 COUNTER SIGNATURE **Signature** CERT. # 8462  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/24/07

SECTION/AREA Main West

TIME OF EXAMINATION START 3:10  AM  PM

END 4:40  AM  PM

EXAM. CALLED OUT — YES/ NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	48360		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			none observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0%	0			none observed	
Transformer	20.8	0%	0			none observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Loose rib	in LOX	sealed

PRE-SHIFT REMARKS all over safe @ time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_  
 SECTION SUPERVISOR \_\_\_\_\_

Signature

CERT. # 9174  
 CERT. # 7488

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-24-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 11:05 AM/PM

END 11:56 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:25 AM/PM

CALLED OUT BY LESTER DAY

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	32775		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS-CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINE

Signature  
Signature

CERT.# 7999

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 24 07

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM

END 859 AM/PM

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME, 931 AM/PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50560		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	α		None observed	
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Trans	Trash accum.	Cleaned
Feeder	Accumulations	Cleaned

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT.# 9279

COUNTER SIGNATURE Signature

CERT.# 03892

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-25-07

SECTION/AREA West mains

TIME OF EXAMINATION START 3:00 AM/PM

END 4:43 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	21.0	0	0	49,760		none	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	21.0	0	0	OK		none	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	21.0	0	0	OK		none	
Charger - Tran	21.0	0	0	OK		none	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#1 entry	Deep water	pump it out
# intake	Hole in #143 stopping	Team it

PRE-SHIFT REMARKS All areas appeared safe at Time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT. #

9279

COUNTER SIGNATURE

Signature

CERT. #

7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

52

2MSHA02802

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-25-07

SECTION/AREA West Mains

TIME OF EXAMINATION START 12:00 AM/PM (PM)

END 1:07 AM/PM (PM)

EXAM. CALLED OUT (YES)/NO

CALL OUT TIME 1:40 AM/PM (PM)

CALLED OUT BY Dale Black

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	54,005		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0	OK		NONE OBSERVED	
TRANS/CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 25 07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 7 AM/PM AM END 856 AM/PM AM  
 EXAM. CALLED OUT — YES/NO CALL OUT TIME 9 40 AM/PM AM  
 CALLED OUT BY Benny Allred REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE	20.9	0	0	51360		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	OK		None observed	
Trans/Charger	20.9	0	0	OK		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
150' OB Pillar line	No warning signs	Installed signs

PRE-SHIFT REMARKS All work areas and travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 9279  
 COUNTER SIGNATURE **Signature** CERT.# 03892  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-26-07

SECTION/AREA Main West

TIME OF EXAMINATION START 3:02  AM  PM

END 4:25  AM  PM

EXAM. CALLED OUT — YES  NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	5,896		NONE OBS	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBS	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillpr line	20.9	0	0	OK		NONE OBS	
TRANS/CHARGER	20.9	0	0	OK		NONE OBS	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
FB.	dirty	Cleaned

PRE-SHIFT REMARKS All work areas and travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_  
 SECTION SUPERVISOR \_\_\_\_\_

Signature

CERT. # 9907  
 CERT. # 05892

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-26-07

SECTION/AREA west Main

TIME OF EXAMINATION START 11:00  AM  PM

END 11:52  AM  PM

EXAM. CALLED OUT —  YES  NO

CALL OUT TIME 125  AM  PM

CALLED OUT BY Dale Bled

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	480 gpm OK		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		none observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	OK		none observed	
trans/chargers	20.9	0	0	OK		none observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Appeared Safe at the time of exam.

PRE-SHIFT/MINE EXAMINEE Signature

COUNTER SIGNATURE \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

CERT. # 7493

CERT. # 03892

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 26 07

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM

END 8:40 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY Benny Alfred

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50616		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	α		None observed	
Trans/Charger	20.9	0	0	α		None observed	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
#3 Entry	Leaking stopping	Repaired

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 9279

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-27-07

SECTION/AREA Main West

TIME OF EXAMINATION START 3:06 AM/PM

END 4:36 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	49,280		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Tranche charge	20.9	0	0	α		None	
Pillar line	20.9	0	0	α		None	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
*1 entry	Deep water	pump water

PRE-SHIFT REMARKS All areas appeared safe at  
Time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ Signature \_\_\_\_\_ CERT.# 9279  
 COUNTER SIGNATURE \_\_\_\_\_ Signature \_\_\_\_\_ CERT.# 7483  
 SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-27-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11:00  AM  PM

END 12:15  AM  PM

EXAM. CALLED OUT —  YES  NO

CALL OUT TIME 1:00  AM  PM

CALLED OUT BY Steve Wilson ~~Steve Wilson~~ Later Day REPORT RECEIVED BY Steve Wilson  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	38736		none observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		none observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Trans./Charger	20.9	0	0	OK		none observed	
Pillar line	20.9	0	0	OK		none observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas reported safe at time of exam.

PRE-SHIFT/MINE EXAMINEE **Signature** CERT.# 9660  
 COUNTER SIGNATURE CERT.# 7483  
 SECTION SUPERVISOR

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 27 07

SECTION/AREA Main West

TIME OF EXAMINATION START 702 AM/PM AM

END 820 AM/PM AM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 949 AM/PM AM

CALLED OUT BY Don Erickson

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX / INTAKE	20.9	0	0	49770		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	0		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	0		None observed	
Travis/Charger	20.9	0	0	0		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#3 entry	2 damaged stoppings	Repaired

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature

COUNTER SIGNATURE \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

CERT. # 9207

CERT. # 05892

2MSHA02810

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-28-07  
 TIME OF EXAMINATION START 3:00 AM/PM  
 EXAM. CALLED OUT — YES/NO  
 CALLED OUT BY \_\_\_\_\_

SECTION/AREA Main west  
 END 4:42 AM/PM  
 CALL OUT TIME \_\_\_\_\_ AM/PM  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/ <del>INTAKE</del>	20.9	0	0	48,640		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	α		None	
Tran-charger	20.9	0	0	α		None	

V= VIOLATION  
 H= HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Belt entry	Accumulation	clean
#7 Belt	Accumulation	shoveled

PRE-SHIFT REMARKS All area appeared safe at  
Time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_  
 SECTION SUPERVISOR \_\_\_\_\_

Signature

CERT. # 9279  
 CERT. # 9483

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-28-07

SECTION/AREA Main West

TIME OF EXAMINATION START 1100  AM/PM

END 1150  AM/PM

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME 1205  AM/PM

CALLED OUT BY Lester Day

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	OK	47048		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	OK			None	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Trans/Charge	20.9	0	OK			None	
Pillar line	20.9	0	OK			" "	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Section reported safe at time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9660

COUNTER SIGNATURE

CERT. # 7483

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 28 07

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM

END 835 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 921 AM/PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY

Signature

  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51040		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	05		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	05		None observed	
Trans/Charger	20.9	0	0	05		None observed	

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
west main	Accumulation MRSs	shot down w/dsh
Tran	Accumulation	clean and dusted

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINEE

Signature

CERT.# 9279

COUNTER SIGNATURE

CERT.# 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-29-07

SECTION/AREA MAIN West

TIME OF EXAMINATION START 3:02  AM  PM

END 4:12  AM  PM

EXAM. CALLED OUT — YES/ NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51,967		None OBS	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None OBS	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar Line	20.9	0	0	OK		None OBS	
TRANS/CHARGER	20.9	0	0	OK		None OBS	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All Work Areas & TRAVELWAYS APPEARED SAFE  
At Time of Exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 9707  
 COUNTER SIGNATURE \_\_\_\_\_ CERT.# 7483  
 SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-29-07

SECTION/AREA Main West

TIME OF EXAMINATION START 1105 AM/PM

END 1215 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME 1240 AM/PM

CALLED OUT BY Feater Day

REPORT RECEIVED BY

Signature

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	ok			None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	ok			None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	ok			None observed	
Trans/Charger	20.9	0	ok			"	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
#2 yr 144	Bad ribs	Took down with CM

PRE-SHIFT REMARKS Section was reported safe at  
time of exam

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 9660

COUNTER SIGNATURE

CERT.# 7483

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7 29 07

SECTION/AREA Main West

TIME OF EXAMINATION START 7 AM/PM

END 850 PM AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 930 AM/PM

CALLED OUT BY Benny Allred

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	5/200	<input checked="" type="radio"/>	None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	0		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	0		None observed	
Trans/Charger	20.9	0	0	0		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#1 entry	Bad ribs	Set timbers

PRE-SHIFT REMARKS All work areas and travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature**

COUNTER SIGNATURE \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

CERT.# 9279

CERT.# 03892

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-30-07

SECTION/AREA MAIN West

TIME OF EXAMINATION START 3:01 AM/PM

END 4:25 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	52,300		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar Line	20.9	0	0	OK		NONE OBSERVED	
TRANS/CHARGER	20.9	0	0	OK		NONE OBSERVED	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work areas and travel way appeared safe  
at time of exam.

PRE-SHIFT/MINE EXAMINEE **Signature** CERT. # 9707

COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4935

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-30-07

SECTION/AREA Main West

TIME OF EXAMINATION START 1655  AM  PM

END 120  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 1:37  AM  PM

CALLED OUT BY Brandon Kimber

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50330		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.7	0	0	OK		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillory Lane	20.9	0	0	OK		None observed	
Trucks/Charger	20.9	0	0	OK		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER Signature

CERT. # 9658

COUNTER SIGNATURE Signature

CERT. # 8462

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-30-07

SECTION/AREA Main West

TIME OF EXAMINATION START 2:00 AM/PM

END 8:55 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 9:15 AM/PM

CALLED OUT BY Josh Fielder

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	50/32		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0	2		None Observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0	2		None Observed	
Transformer	20.8	0	0	2		None Observed	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
Feeder	Acc	Cleaned
Pillar line	Oxy/Acet tanks	removed
Bud rib	#1 entry	sealed

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of Exam.

PRE-SHIFT/MINE EXAM  
COUNTER SIGNATURE  
SECTION SUPERVISOR **Signature**

CERT.# 9174  
CERT.# 8462

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/31/07

SECTION/AREA Mann West

TIME OF EXAMINATION START 3:15 ~~AM~~ PM

END 4:15 ~~AM~~ PM

EXAM. CALLED OUT — YES/~~NO~~

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	50500		none ok	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			none ok	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0%	0			none ok	
Transformer	20.8	0%	0			need guarded out by tub HV under 6.5'	guarded reported

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas reasonably safe for work & travel.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9174  
 COUNTER SIGNATURE \_\_\_\_\_ CERT. # 4735  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7/31/07

SECTION/AREA V. WEST MINE-15

TIME OF EXAMINATION START 1119 AM/PM

END 1254 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50.842		1-LOW O <sub>2</sub>	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			1-LOW O <sub>2</sub>	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
TRANSFORMER	20.9	0	0			1-LOW O <sub>2</sub>	
RECLAM LINE	20.9	0	0			1-LOW O <sub>2</sub>	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
1-PROX	ACCUM	CLEANED

PRE-SHIFT REMARKS ALL AREAS APPROPRIATELY SAFE AT  
END OF EXAM

PRE-SHIFT/MINE EXAMINER  
COUNTER SIGNATURE  
SECTION SUPERVISOR

Signature

CERT. # 7658  
CERT. # 8762

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 7-31-07

SECTION/AREA Main West

TIME OF EXAMINATION START 7:00 AM/PM

END 8:35 AM/PM

EXAM. CALLED OUT —  YES/NO

CALL OUT TIME 9:50 AM/PM

CALLED OUT BY Josh Fielder

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX / INTAKE	20.8	0	0	49388		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None Observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0			None Observed	
Transformer	20.8	0	0			None Observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Fielder	acc	cleaned

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature**  
 COUNTER SIGNATURE **Signature**  
 SECTION SUPERVISOR

CERT.# 9174  
 CERT.# 8462

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8/1/07

SECTION/AREA Main West

TIME OF EXAMINATION START 3:15  AM  PM

END 4:30  AM  PM

EXAM. CALLED OUT — YES/ NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	50 @ 82		none ob.	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			none ob.	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
transformer	20.8	0%	0			none ob.	
Pillar line	20.8	0%	0			none ob.	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas safe @ time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT.# 9174

COUNTER SIGNATURE \_\_\_\_\_ CERT.# 4135

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-1-07  
 TIME OF EXAMINATION START 12.00 AM/PM  
 EXAM. CALLED OUT —  YES / NO  
 CALLED OUT BY Brandon Kimber REPORT RECEIVED BY

SECTION/AREA Main West  
 END 1.40 AM/PM  
 CALL OUT TIME 1.45 AM/PM  
 Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51072		none obs	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			none obs	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillars Line	20.9	0	0			None obs	
TRAPS	20.9	0	0			None obs	

V = VIOLATION  
 H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

PRE-SHIFT/MINE EXAMINER Signature  
 COUNTER SIGNATURE Signature  
 SECTION SUPERVISOR Signature

CERT. # 9658

CERT. # 8462

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-1-07  
 TIME OF EXAMINATION START 2:00 AM/PM   
 EXAM. CALLED OUT  YES/NO  
 CALLED OUT BY Josh Fielder

SECTION/AREA Main West  
 END 9:00 AM/PM   
 CALL OUT TIME 9:48 AM/PM   
 REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	51000		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0	0			None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0			None observed	
Transformer	20.8	0	0			None observed	

V = VIOLATION  
 H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Pillar line	Bad rib	scabed

PRE-SHIFT REMARKS all areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER **Signature**  
 COUNTER SIGNATURE **Signature**  
 SECTION SUPERVISOR **Signature**

CERT. # 9174  
 CERT. # 8462

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8/2/67  
 TIME OF EXAMINATION START 340 AM/PM  
 EXAM. CALLED OUT — YES/NO (NO)  
 CALLED OUT BY \_\_\_\_\_

SECTION/AREA Mans Lake  
 END 445 AM/PM  
 CALL OUT TIME \_\_\_\_\_ AM/PM  
 REPORT RECEIVED BY \_\_\_\_\_  
 SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	51,200		Water in intake getting deep	reported
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			Return stopping down	hung rag, but needs rebuilt Dave D
#1 ENTRY							
#2 ENTRY						Accumulation between 2 to 3 entries	reported
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
transformer	20.8	0%	0			none ob	
Pillar line	20.8	0%	0			none ob	

V = VIOLATION  
 H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
ret stopping	downed	rebuilt

PRE-SHIFT REMARKS areas reasonably safe for work & travel

PRE-SHIFT/MINE EXAMINEE **Signature** CERT.# 9174  
 COUNTER SIGNATURE \_\_\_\_\_ CERT.# 4935  
 SECTION SUPERVISOR \_\_\_\_\_  
 INITIALS (NOT REQUIRED) \_\_\_\_\_ 76

2MSHA02826

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-2-07

SECTION/AREA Main West

TIME OF EXAMINATION START 11.56 (AM/PM)

END 1.09 (AM/PM)

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 1.37 (AM/PM)

CALLED OUT BY Brandon Kimber REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	52234		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
trams	20.9	0	0			None observed	
pillar line	20.9	0	0			None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
BELT LINE	No Box Check	HUNG TAG

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9658

COUNTER SIGNATURE Signature CERT. # 8462

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-2-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START 9:45 AM/PM END 9:55 AM/PM  
 EXAM. CALLED OUT —  YES/NO CALL OUT TIME 9:56 AM/PM  
 CALLED OUT BY Josh Fielder REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0	0	51035		Deep water 140	Pumped and scooped
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.8	0	0			None Observed	
Trans Former	20.8	0	0			None Observed	

V= VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
<del>one</del> section roadways	acc in section roadways	Cleaned with scoop
Feeder	ACC	Cleaned

**Signature**

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of exam

**Signature**

PRE-SHIFT/MINE EXAMINER **Signature** CERT.# 9174  
 COUNTER SIGNATURE **Signature** CERT.# 8462  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8/3/07

SECTION/AREA Main West

TIME OF EXAMINATION START 330  AM  PM

END 430  AM  PM

EXAM. CALLED OUT — YES  NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.8	0%	0	50/88		none ob	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.8	0%	0			diagonal stopping needs repaired (bounce)	SENT MEN TO REPAIR DONE
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
transformer	20.8	0%	0			none ob	
Pillar line	20.8	0%	0			none ob	

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS areas reasonably safe, need additional  
timber along pillar mining on.

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_

Signature

CERT. # 9174

COUNTER SIGNATURE \_\_\_\_\_

CERT. # 7485

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-3-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 11:10 AM/PM

END 12:30 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:50 AM/PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	46410		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0			NONE OBSERVED	
TRANS/CHARGER	20.9	0	0			NONE OBSERVED	

V= VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION
FEEDER	ACCUMULATIONS	CLEANED

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8307

SECTION/AREA Main West

TIME OF EXAMINATION START 710 AM/PM

END 845 AM/PM

EXAM. CALLED OUT  YES/NO

CALL OUT TIME 943 AM/PM

CALLED OUT BY Benny Alvord

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	21	0	0	51940		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	21	0	0	05		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	21	0	0	05		None observed	
Trans/Charger	21	0	0	05		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
main west	Bad rib	Bar down

PRE-SHIFT REMARKS All work areas & travelways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9279

COUNTER SIGNATURE

CERT. # 03892

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-4-07

SECTION/AREA MAIN West

TIME OF EXAMINATION START 3:02  AM  PM

END 4:15  AM  PM

EXAM. CALLED OUT — YES/ NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50,740		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None Observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar Line	20.9	0	0	OK		None Observed	
TRANS / CHARGER	20.9	0	0	OK		None Observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work Areas & Travelways Appeared Safe At Time of Exam

PRE-SHIFT/MINE EXAMINEE **Signature** CERT.# 9707  
 COUNTER SIGNATURE \_\_\_\_\_ CERT.# 7485  
 SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-4-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 11:00  AM  PM

END 11:54  AM  PM

EXAM. CALLED OUT  YES  NO

CALL OUT TIME 1:45  AM  PM

CALLED OUT BY DALE BLACK

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	47630		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0			NONE OBSERVED	
TRANS-CHARGER	20.9	0	0			NONE OBSERVED	

V = VIOLATION  
H = HAZARD

### ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 7483

COUNTER SIGNATURE

CERT. # 7485

SECTION SUPERVISOR

2MSHA02833

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8 4 07

SECTION/AREA Main West

TIME OF EXAMINATION START 703 AM/PM (AM)

END 810 AM/PM (AM)

EXAM. CALLED OUT YES/NO

CALL OUT TIME 906 AM/PM (AM)

CALLED OUT BY Don Erickson

REPORT RECEIVED BY **Signature**

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51934		None observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	05		None observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	05		None observed	
Trans/Charger	20.9	0	0	05		None observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
#1 entry	tripping hazards	removed

PRE-SHIFT REMARKS All work areas & travel ways appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER **Signature**

CERT. # 9207

COUNTER SIGNATURE **Signature**

CERT. # 03892

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-25-07

SECTION/AREA MAIN West

TIME OF EXAMINATION START 3:03 AM/PM

END 4:10 AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	50,780		None Observed	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	OK		None Observed	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	OK		None Observed	
TRANS / CHARGER	20.9	0	0	OK		None Observed	

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS All work Areas + Travelways appeared safe  
At Time of Exam.

PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9207

COUNTER SIGNATURE

CERT. # 7488

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-5-07

SECTION/AREA MAIN WEST

TIME OF EXAMINATION START 1103 AM/PM

END 1226 AM/PM

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:00 AM/PM

CALLED OUT BY Dale Black

REPORT RECEIVED BY

Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	49710		NONE OBSERVED	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0			NONE OBSERVED	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
PILLAR LINE	20.9	0	0			NONE OBSERVED	
TRANS-CHARGER	20.9	0	0			NONE OBSERVED	

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT  
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER

Signature

CERT.# 7483

COUNTER SIGNATURE

CERT.# 7485

SECTION SUPERVISOR

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-5-07

SECTION/AREA Main west

TIME OF EXAMINATION START 7:01 AM/PM

END 7:48 AM/PM

EXAM. CALLED OUT — YES/NO YES  
 CALLED OUT BY Don Erickson

CALL OUT TIME 9:00 AM/PM

CALLED OUT BY Signature

REPORT RECEIVED BY Signature

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE	20.9	0	0	51,340		None	
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN	20.9	0	0	α		None	
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							
Pillar line	20.9	0	0	α		None	
Tran charger	20.9	0	0	α		None	

V = VIOLATION  
 H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION
Main west	Feeder accumulation	cleaned

PRE-SHIFT REMARKS All area reported safe at  
Time of exam

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION 8-6-07 SECTION/AREA Main West  
 TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM  
 EXAM. CALLED OUT — YES/NO CALL OUT TIME \_\_\_\_\_ AM/PM  
 CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS Section Idle with K order due to seismic activity

Signature

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_  
 COUNTER SIGNATURE \_\_\_\_\_  
 SECTION SUPERVISOR \_\_\_\_\_

CERT. # \_\_\_\_\_  
 CERT. # 8-6-07

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_ SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

\_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_

SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_ SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO \_\_\_\_\_ CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

\_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_ SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_

SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_

SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_ SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO \_\_\_\_\_ CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_  
SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

\_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_

SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO \_\_\_\_\_

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_

REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_

SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_ SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V= VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_

SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM

END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO

CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_

SIGNATURE

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX/INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

# PRE-SHIFT SECTIONS

DATE OF EXAMINATION \_\_\_\_\_ SECTION/AREA \_\_\_\_\_

TIME OF EXAMINATION START \_\_\_\_\_ AM/PM END \_\_\_\_\_ AM/PM

EXAM. CALLED OUT — YES/NO \_\_\_\_\_ CALL OUT TIME \_\_\_\_\_ AM/PM

CALLED OUT BY \_\_\_\_\_ REPORT RECEIVED BY \_\_\_\_\_ SIGNATURE \_\_\_\_\_

LOCATIONS	O <sub>2</sub>	CH <sub>4</sub> %	CO	CFM/AIR DIRECTION	V or H	HAZARD CONDITIONS	ACTION TAKEN
LOX /INTAKE							
HEADGATE #10							
TAILGATE #126							
BELTLINE							
RETURN							
#1 ENTRY							
#2 ENTRY							
#3 ENRTY							
#4 ENTRY							
#5 ENTRY							
#6 ENTRY							

V = VIOLATION  
H = HAZARD

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATIONS	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

\_\_\_\_\_

PRE-SHIFT/MINE EXAMINER \_\_\_\_\_ CERT. # \_\_\_\_\_

COUNTER SIGNATURE \_\_\_\_\_ CERT. # \_\_\_\_\_

SECTION SUPERVISOR \_\_\_\_\_

INITIALS (NOT REQUIRED)

2MSHA02851