Mine Citation/Order

22. Signature

Patrick Alan Stanfield

U.S. Department of Labor



Mine Safety and Health Administration Section I-Violation Data 2. Time (24 Hr. Clock) 3. Citation/ 1. Date Mo Da Yr 4900300 Order Number 0800 12/06/2011 5. Operator 4. Served To PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 6. Mine 7. Mine ID 46-08436 UPPER BIG BRANCH MINE-SOUTH (Contractor) 8a. Written Notice (103g) 8. Condition or Practice An agent of the Operator (Qualified Electrician) failed to make a monthly test, and examination of these low/medium voltage circuit breakers during the month prior to 04.05.2010; AEEI (American Electric Equipment, Inc) distribution box (company #HG-22), 480 volt circuit breaker used to power the scoop battery charger, (2) five circuit breakers installed in the Distribution box labeled as "Outby" fails to reflect the circuit breakers were tested during the month prior to The D-box is located near the discharge boom (left side of the April 2010. track) for HG22 section belt-near spad #24356). The circuit breakers supply 480 volts to a welder and two battery chargers. (3) Low/medium voltage circuit breakers installed in AEEI (American Electric Equipment, Inc.), serial #22908-1200-1005. This power center is See Continuation Form (MSHA Form 7000-3a) B. Section C. Part/Section of 9. Violation A. Health of Act Title 30 CFR 75.900-3 Safety 🗸 Other Section II--Inspector's Evaluation 10. Gravity: Occurred Highly Llkely A. Injury or Illness (has) (is): No Likelihood Unlikely -Reasonably Likely 🗸 B. Injury or illness could rea-No Lost Workdays Lost Workdays Or Restricted Duty Permanently Disabling 🗸 Fatal sonably be expected to be: D. Number of Persons Affected: C. Significant and Substantial: 001 Yes 🗸 No 🗌 11. Negligence (check one) A. None C. Moderate B. Low D. High E. Reckless Disregard 13. Type of Issuance (check one) Citation 🗸 Order -Safeguard Written Notice 12. Type of Action 104(a) F. Citation/ F. Dated Mo Da Yr 14. Initial Action Order Number A. Citation B. Order C. Safeguard D. Written Notice 15. Area or Equipment Mo Da Yr 16. Termination Due A. Date B. Time (24 Hr. Clock) 0800 01/05/2012 Section III--Termination Action 17. Action to Terminate Mo Da Yr 18. Terminated A. Date B. Time (24 Hr. Clock Section IV--Automated System Data 19. Type of Inspection 20. Event Number 21. Primary or Mill 4440348 E16 (activity code)

In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has MSHA Form 7000-3, Apr 08 (revised) established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

23. AR Number

23908

Mine Citation/Order Continuation

U.S. Department of LaborMine Safety and Health Administration



Section I—Subsequent Action/Continuation Data							
1. Subsequent Acti	on 1a. Continuation ✓	Dated (Original Issue)	Mo Da 12/06/2	Yr 011	3. Citation/ Order Number 4900300		
4. Served To				5. Opera	5. Operator		
Berman Cornett (Safety Director)				PERFC	PERFORMANCE COAL COMPANY, et al		
6. Mine				7. Mine II	D 46.00426	(Contractor)	
UPPER BIG BRANCH MINE-SOUTH					46-08436		
Section II. Justification for Action							

Continuation of 8. Condition or Practice

located at the mouth of HG 22.

This equipment is all located in the area affected by a mine explosion on 04.05.2010.

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

			See Continuation Form		
Section III-Subsequent Action Taken					
8. Extended To A. Date Mo Da	Yr B. Time (24 Hr. Clock)	C. Vacated	C. Vacated D. Terminated E. Modified		
Section IV-Inspection Data					
9. Type of Inspection E16	10. Event Number 4440348	1			
11. Signature	AR Number	12. Date Mo Da Yr	13. Time (24 Hr. Clock)		
Patrick Alan Stanfield	23908	12/06/2011	0800		