Mine Citation/Order

U.S. Department of Labor Mine Safety and Health Administration



Section I--Violation Data 3. Citation/ 1. Date 2. Time (24 Hr. Clock) Mo Da Yr 8257000 Order Number 12/06/2011 0800 4. Served To 5. Operator PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 7. Mine ID 6. Mine 46-08436 (Contractor) UPPER BIG BRANCH MINE-SOUTH 8a. Written Notice (103g) 8. Condition or Practice

The 225 amp AEEI disconnect for the Joy Shuttle car (serial #ET17017) has the front lip partially broken. The hole for locking/tagging is broken off. The back of the outer shell is also broken where the cable is attached to the disconnect. The disconnect is lying in the conveyor of the car. The car is located near the Mother Drive Construction Area on the North mains adjacent to spad #20406.

The car is located in an area affected by an explosion on 04.05.2010. The car was not in use on 04.05.2010, however it is readily available for use. The trailing cable disconnect is in the conveyor of the car. It is within reach of a power center to where it can be connected.

This citation is being issued to the following entities as a unitary See Continuation Form (MSHA Form 7000-3a) C. Part/Section of 9. Violation B. Section A. Health Safety 🗸 Title 30 CFR 75.511 of Act Other -Section II-Inspector's Evaluation 10. Gravity: A. Injury or Illness (has) (is): No Likelihood Unlikely 🗸 Reasonably Likely Highly Likely Occurred B. Injury or illness could rea-No Lost Workdays Lost Workdays Or Restricted Duty Permanently Disabling Fatal sonably be expected to be: D. Number of Persons Affected: C. Significant and Substantial: 001 Yes 🗌 No 🗸 11. Negligence (check one) A. None B. Low C. Moderate D. High E. Reckless Disregard 12. Type of Action 13. Type of Issuance (check one) Citation 🗸 Order Safeguard Written Notice 104(a) 14. Initial Action E. Citation/ F. Dated Mo Da Yr A. Citation B. Order C. Safeguard D. Written Notice Order Number 15. Area or Equipment 16. Termination Due Mo Da Yr A. Date B. Time (24 Hr. Clock) 0800 01/05/2012 Section III-Termination Action 17. Action to Terminate 18. Terminated Mo Da Yr A. Date B. Time (24 Hr. Clock Section IV--Automated System Data 19. Type of Inspection 20. Event Number 21. Primary or Mill 4440348 E16 (activity code) 22. Signature 23. AR Number Patrick Alan Stanfield 23908

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order Continuation

U.S. Department of LaborMine Safety and Health Administration



Section ISubsequent Action/Continuation Data							
1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Mo D 12/06/	a Yr 2011	3. Citation/ Order Number	8257000		
4. Served To			5. Opera	5. Operator			
Berman Cornett (Safety Director)				PERFORMANCE COAL COMPANY, et al			
6. Mine			7. Mine I	D 46 00 40		(Contractor)	
UPPER BIG BRANCH MINE-SOUTH				46-0843	6		
Section II-Justification for Action							

Continuation of 8. Condition or Practice

operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

					See Continuation Form
Section IIISubsequent Action Taken					
8. Extended To A. Date Mo Da Yr B. Time	Yr B. Time (24 Hr. Clock)		C. Vacated	D. Terminated	E. Modified
Section IV—Inspection Data	·		'		
9. Type of Inspection E16	ber 4440348		4	·	
11. Signature	AR Number	12. Date	Mo Da Yr	13. Time (24 Hr. Clo	ck)
Patrick Alan Stanfield	23908		12/06/2011	0800	