

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4117123Company Name Performance LandMine Name Upper Big Branch MineMine I.D. Number 46-08436

Date(s) of Mine File Review _____

D Status _____ Citation/Order No. _____ Date _____

Dates of Inspection: began 4-18-07 completed 4-18-07Pre-Inspection Conference Date 4-18-07Company Representative(s) Rick Hodge,
Bill Harless

Miners Representative(s) _____

Post-Inspection Conference Date 4-18-07

Company Representative(s) _____

Miners Representative(s) _____

Comments: _____

Inspector's Initials _____ Supervisor's Initials and Date KSA

*U.S. Government Printing Office: 1995 - 609-287

DAILY COVER SHEET

Date 4-18-07 Event No. 4117123

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked weekly

Accompanied By: Company Representative _____

Miners Representative _____

AREAS OF INSPECTION ACTIVITY:

Traveled truck from
portal to break 74.
Entered return & traveled
to North Mains heading

Inspector's Initials _____

Supervisor's Initials and Date KSA Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

Date 4-18-07209 V Break 74114.4 A Return from23,909.6 North Mainsheading20.8 .45 CH4 9:25R6764 R6763✓ Flygt switch M01-0123at break 76 OK✓ SP5 pump serial 051003break 76 - not in service OK✓ Flygt switch M06-0269 atbreak 85 - OK✓ Flygt pump 26044 atbreak 85 - OKDates were observed from2/7 to 4/11 on 7-day cycle

Inspector's Initials _____

Supervisor's Initials and Date KSA Page No. 2

GPO U.S. GPO: 2009-543-041

Date 4-18-07North Mains sectionLOB 5-6 .2% CH420.8 11:20.160 A79 V12,640✓ Flygt pump in face of No. 4Made faces 6-1 .3% CH420.8 O2 DT4 I presentNorth Mains sectionSection settling idle1 minerNo. 5 SC ET16962No. 6 SC ET16945Freden No. 2 (13018R2)No. 3 SC ET17017

Inspector's Initials _____

Supervisor's Initials and Date KSA Page No. 3

GPO U.S. GPO: 2009-543-041

Date 4-18-07No power on section✓ Blower switch SN 5839 atbreak 137 in intake OK✓ pump at break 137 OK✓ AEEI 22938-206 trans-former on North Mains 5at break 75 NVO

Inspector's Initials _____

Supervisor's Initials and Date KSA Page No. 4

GPO U.S. GPO: 2009-543-041