



Notes:
 Ventilation controls depicted as mapped during the investigation. Alterations to permanent ventilation controls made during rescue and firefighting operations are shown in blue.



APPENDIX C
 ARACOMA ALMA MINE #FL MSHA ID No. 46-08601
 ARACOMA COAL COMPANY, INC.
 Area Surrounding 9 Headgate Longwall Section and 2 Section

LEGEND

- Primary Escapeway Reflective Tag
- Roof Fall
- Cribs
- Survey Station (SS) Location and Number
- Roadway
- Stopping
- Hole in Ventilation Control Indicated by Slash
- Stopping with Personnel Door
- Box Check Stopping
- Overcast
- Overcast with Personnel Doors
- Set of Equipment Doors
- Regulator
- Seal
- Check Curtain
- Installed Conveyor Belt
- Installed Belt Structure