

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification: Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident: 08/02/2014 11:00 AM		4. Date/Time of Death: 08/02/2014 11:00 AM		5. Fatal Case No: 17						
6. Mine Information :														
a) Mining Company Name: Fossum Ready Mix			b) Mine Name: Belzer Pit			c) Parent of Mining Company: Steve Fossum; Scott Fossum; Carol Fossum								
7. Mine Location :		a) City: Glasgow		b) County: Valley		c) State: MT		8. Mine ID Number: 24-00420		9. Union: NO				
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total: 2		b) Underground: 0		c) Open Pit/Quarry: 2		d) Mill/Prep Plant: 0		e) Other: 0	
12. Contractor Name:						13. Union:		14. Contractor ID Number:						
15. Contractor Address:		a) City:		b) County:		c) State:		d) Zip Code:						
16. Number of Contractor Employees:					a) Total:		b) Underground:		c) Open Pit/Quarry:		d) Mill/Prep Plant:		e) Other:	
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:								
a) Mine Employees: 1		b) Contractor Employees: 0		a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident:								20. Mining Height:						
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet		Inches		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility								
21. Nonfatal Injuries:			22. Fatal Injuries: 1											
23. Victim Information :				a) Name: Robert L. Irwin		b) Age: 53								
c) Regular Job Title: Plant Operator				d) Activity at Time of Accident: Working under raised truck bed				<input checked="" type="checkbox"/> Mine Employee						
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days						
a) Total:		25 4 2		b) at the mine:		25 4 2		c) at activity (23d):		25 4 2		d) with Contractor:		
25. Autopsy Performed: If Yes, Location: NO								26. Mine Telephone No.: (406) 228-8038						

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
The victim was working under the raised bed of a dump truck when the wooden block supporting the bed suddenly failed, pinning him. The victim was working alone and was not found until 10 a.m. on August 3, 2014.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: International Harvester				29. Model: Loadstar							
30. District: M6000 Rocky Mountain		32. Field Office: Rapid City SD				33. Event Number: 6692804					
34. Accident Investigator: David Small				35. MSHA Person Notified: Dustan Crely				Date: 08/03/2014		Time: 01:21 P	
36. Type of Report: Amended			37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>				Date: 08/15/2014				
38. Reason For Amendment: Items 23 a, b											