

Preliminary Report of Accident



| | | | | | | | | | | |
|---|--|--|---|---|--|---|---|---|--------------------------|------------------|
| 1. Accident Type: Fatal Injury | | 2. Accident Classification Falling, Rolling or Sliding Rock /Materl | | 3. Date/Time of Accident 08/03/2017 01:30 AM | | 4. Date/Time of Death 08/03/2017 03:23 AM | | 5. Fatal Case No 11 | | |
| 6. Mine Information : | | | | | | | | | | |
| a) Mining Company Name Blue Mountain Energy Inc | | | b) Mine Name Deserado Mine | | | c) Parent of Mining Company Deseret Generation & Transmission Co-operative | | | | |
| 7. Mine Location : | | a) City Rangely | | b) County Rio Blanco | | c) State CO | | 8. Mine ID Number: 05-03505 | | 9. Union: YES |
| 10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND | | | 11. Number of Mine Employees: | | a) Total 161 | b) Underground 101 | c) Open Pit/Quarry 48 | | d) Mill/Prep Plant 12 | e) Other 12 |
| 12. Contractor Name: | | | | | | 13. Union | | 14. Contractor ID Number: | | |
| 15. Contractor Address: | | | | a) City | | b) County | | c) State | | d) Zip Code |
| 16. Number of Contractor Employees: | | | | | a) Total 8 | b) Underground 0 | c) Open Pit/Quarry 0 | d) Mill/Prep Plant 8 | e) Other 0 | |
| 17. Number of Persons in Mine at Time of Accident: | | | | | | 18. Number of Persons Unaccounted For: | | | | |
| a) Mine Employees: 36 | | b) Contractor Employees: 8 | | a) Mine Employees: 0 | | b) Contractor Employees: 0 | | | | |
| 19) Location of Accident | | | | | | | | | 20. Mining Height: | |
| <input type="checkbox"/> 01-Underground | <input type="checkbox"/> 02-Surface at Underground | <input type="checkbox"/> 03-Open Pit | <input type="checkbox"/> 04-Dredge Mining | <input type="checkbox"/> 05-Advance Mining | <input type="checkbox"/> 06-Retreat Mining | <input checked="" type="checkbox"/> 07-Mill/Prep Plant | <input type="checkbox"/> 08-Office Facility | <input type="checkbox"/> Other (specify) | Feet 10 | Inches 0 |
| 21. Nonfatal Injuries: 0 | | | 22. Fatal Injuries: 1 | | | | | | | |
| 23. Victim Information : | | | | | | | | | | |
| a) Name Jason D. Stevens | | | | | b) Age 32 | | | | | |
| c) Regular Job Title: Surface Mechanic | | | | d) Activity at Time of Accident: Cutting Metal | | | | <input checked="" type="checkbox"/> Mine Employee | | |
| 24. Experience : | | | | | | | | | | |
| Years | | Weeks | | Days | | Years | | Weeks | | Days |
| a) Total: | | 6 | | 20 | | b) at the mine: | | 6 | | 20 |
| c) at activity (23d) | | 2 | | 23 | | d) with Contractor | | | | |
| 25. Autopsy Performed: If Yes, Location YES Community Hospital, Grand Junction, Colorado | | | | | | 26. Mine Telephone No.: (970) 675-4346 | | | | |

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On August 3, 2017, a miner was fatally crushed while he was dismantling a metal structure used to supply water to the fine coal filter at the preparation plant.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

| | | | | | | | |
|---|--|--|--|--|------------------------------|--------------------|------------------|
| 28. Equipment Manufacturer: | | | | 29. Model: | | | |
| 30. District: C0900 Denver | | 32. Field Office: Craig CO | | | 33. Event Number: 6460002 | | |
| 34. Accident Investigator: Tain Curtis | | | | 35. MSHA Person Notified: Matt Lemons | | Date 08/03/2017 | Time 01:54 AM |
| 36. Type of Report: Initial | | 37. Name of Preparer and Date Prepared: Tain Curtis | | | | Date 08/03/2017 | |
| 38. Reason For Amendment: | | | | | | | |