

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 02/03/2017 07:25 AM		4. Date/Time of Death 02/10/2017 12:45 PM		5. Fatal Case No 2					
6. Mine Information :													
a) Mining Company Name Greenbrier Minerals, LLC			b) Mine Name Elk Lick Tipple			c) Parent of Mining Company Coronado coal, LLC							
7. Mine Location : a) City Colorado			b) County Logan		c) State WV		8. Mine ID Number: 46-04315		9. Union: NO				
10. Primary Mineral Mined: BITUMINOUS			11. Number of Mine Employees: a) Total 13		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant 13				
12. Contractor Name: Stacy Equipment and Repairs, Inc.						13. Union NO		14. Contractor ID Number: K306					
15. Contractor Address: Gilbert			a) City Mingo			b) County WV		c) State 25621-0000					
16. Number of Contractor Employees:		a) Total 5		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant 5					
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:								
a) Mine Employees: 4		b) Contractor Employees: 1			a) Mine Employees: 0		b) Contractor Employees: 0						
19. Location of Accident								20. Mining Height:					
<input type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input checked="" type="checkbox"/> Other (specify)					
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Loadout Facility					
21. Nonfatal Injuries:			22. Fatal Injuries: 1										
23. Victim Information :													
a) Name Franklin L. Vannoy			b) Age 54										
c) Regular Job Title: Truck Driver				d) Activity at Time of Accident: Truck Driver									
<input checked="" type="checkbox"/> Contractor Employee													
24. Experience :													
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days				
a) Total:		10	3	b) at the mine:		3	c) at activity (23d)		10	3	d) with Contractor		3
25. Autopsy Performed:						26. Mine Telephone No.:							
If Yes, Location						(304) 583-5732							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

An accident occurred at this mine site on 02-03-2017 at 07:25 am that resulted in the death of Franklin L. Vannoy. The victim was operating the Red Mack Granite Coal Truck, Tractor VIN 1M2AG10Y55M021935, Trailer VIN 1E1D2S386YR28120 when the truck overturned while dumping. The victim jumped from the truck as the truck over turned on the truck dump. The victim was transported by Air Evac via helicopter to CMAC General Hospital in Charleston, WV where he passed away on 02-10-2017 from injuries sustained during the accident.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Not listed			29. Model: Granite		
30. District: C1200 Pineville		32. Field Office: Logan WV			33. Event Number: 6308048
34. Accident Investigator: Curtiss Vance III			35. MSHA Person Notified: Katy Trent		Date 02/03/2017
					Time 07:44 A
36. Type of Report: Amended		37. Name of Preparer and Date Prepared Curtiss Vance III			Date 02/13/2017

38. Reason For Amendment:

Initially this was a non fatal accident.