

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Striking or Bumping		3. Date/Time of Accident 06/12/2015 07:30 AM		4. Date/Time of Death 06/13/2015 05:30 PM		5. Fatal Case No 8							
6. Mine Information :															
a) Mining Company Name Fillmore Industries Inc			b) Mine Name Fillmore Pit & Plant			c) Parent of Mining Company Gregory S Fillmore									
7. Mine Location :		a) City Loudon		b) County Merrimack		c) State NH		8. Mine ID Number: 27-00222		9. Union: NO					
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 6	b) Underground 0	c) Open Pit/Quarry 3	d) Mill/Prep Plant 0	e) Other 3						
12. Contractor Name: Southworth-Milton CAT						13. Union YES		14. Contractor ID Number: KPH							
15. Contractor Address:		a) City Hopkinton		b) County Merrimack		c) State NH		d) Zip Code 03229							
16. Number of Contractor Employees:			a) Total 1	b) Underground 0	c) Open Pit/Quarry 1	d) Mill/Prep Plant 0	e) Other 0								
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 6		b) Contractor Employees: 1			a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident									20. Mining Height:						
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches									
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility												
21. Nonfatal Injuries:			22. Fatal Injuries: 1												
23. Victim Information :															
a) Name Laurence D. Yeaton					b) Age 66										
c) Regular Job Title: Service Mechanic															
d) Activity at Time of Accident: Mobile Equipment Maintenance <input checked="" type="checkbox"/> Contractor Employee															
24. Experience :															
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days						
a) Total:	42	30	3	b) at the mine:	22	0	0	c) at activity (23d)	42	30	3	d) with Contractor	42	30	3
25. Autopsy Performed: NO								26. Mine Telephone No.: (603) 783-4723							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was assigned to make minor repairs on six haul trucks to prepare them for sale. When he completed repairs on the first truck, he started working on the second truck and needed a part from the mine's onsite scrap yard. Sometime during the repairs, the victim hit his head but continued to work. At approximately 1:00 p.m., the victim was found unconscious at the scrap yard. The victim was transported by EMS to a local hospital where he died the next day.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 769C		
30. District: M2000 Northeastern		32. Field Office: Manchester NH			33. Event Number: 6685135
34. Accident Investigator: Daniel F. Pullen			35. MSHA Person Notified: Victor C. Lescznske		Date 06/12/2015
36. Type of Report: Initial			37. Name of Preparer and Date Prepared Joseph M. Denk		Date 06/15/2015
38. Reason For Amendment:					