

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 03/24/2017 08:30 PM		4. Date/Time of Death 03/27/2017 09:06 AM		5. Fatal Case No 3			
6. Mine Information :											
a) Mining Company Name Black Rock Services			b) Mine Name Bonito Pit			c) Parent of Mining Company Kayla Kersey; Dale Armstrong					
7. Mine Location :		a) City Los Lunas		b) County Valencia		c) State NM		8. Mine ID Number: 29-02450		9. Union: NO	
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 7	b) Underground	c) Open Pit/Quarry 7	d) Mill/Prep Plant		e) Other	
12. Contractor Name:						13. Union		14. Contractor ID Number:			
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code			
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:						
a) Mine Employees: 1		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees:				
19) Location of Accident									20. Mining Height:		
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility						
21. Nonfatal Injuries:			22. Fatal Injuries:			1					
23. Victim Information :				a) Name Steve Justice		b) Age 53					
c) Regular Job Title: Crusher Operator			d) Activity at Time of Accident: Turning off Diesel Generator			<input checked="" type="checkbox"/> Mine Employee					
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days			
a) Total:		2 26 0		b) at the mine:		1 6 5		c) at activity (23d)		1 6 5	d) with Contractor
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.: (505) 313-2404					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

Victim exited his personal flat bed truck, which was left running in 6th gear, to turn off the genset(diesel generator) on Friday (3/24/17). Prior to ascending the steps to the diesel generator, it appears the flat bed truck moved forward and pinned him against the genset building. The victim was found on Monday (3/27/17) and pronounced dead at the scene.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Dodge			29. Model: 3500 Flat Bed Truck			
30. District: M5000 South Central		32. Field Office: Albuquerque NM			33. Event Number: 6736462	
34. Accident Investigator: Darwin Bratcher			35. MSHA Person Notified: Mark Williams		Date 03/27/2017	Time 09:20 AM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Elwood M. Burriss			Date 03/27/2017	
38. Reason For Amendment:						