

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 06/08/2017 08:00 AM		4. Date/Time of Death 06/08/2017 08:00 AM		5. Fatal Case No 4		
6. Mine Information :										
a) Mining Company Name Hastie Mining			b) Mine Name Hastie Mine			c) Parent of Mining Company Donald D. Hastie; Robert L. Hastie				
7. Mine Location :		a) City Cave-In-Rock		b) County Hardin		c) State IL		8. Mine ID Number: 11-01023		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees:		a) Total 31	b) Underground 0	c) Open Pit/Quarry 12		d) Mill/Prep Plant 2	e) Other 17
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total 6	b) Underground 0	c) Open Pit/Quarry 6	d) Mill/Prep Plant 0	e) Other 0			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 26		b) Contractor Employees: 6			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height: Feet Inches	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)			
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name James H. Mangus, Jr.					b) Age 56					
c) Regular Job Title: Truck Driver			d) Activity at Time of Accident: Truck Driver				<input checked="" type="checkbox"/> Mine Employee			
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total:	3 8 0		b) at the mine:	3 8 0		c) at activity (23d)	3 8 0		d) with Contractor 0 0 0	
25. Autopsy Performed: If Yes, Location YES Williamson County Morgue						26. Mine Telephone No.: (618) 289-4536				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating a Caterpillar 777F haul truck, dumping a load of gravel at a dump point, when the ground at the dump began to slough. The truck went over the edge of the dump point, overturning and landing on the roof of the truck approximately 30 feet below. The victim was transported to the hospital, where he later died of his injuries.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar				29. Model: 777F			
30. District: M4000 North Central		32. Field Office: Peru IL			33. Event Number: 6742124		
34. Accident Investigator: James A. Hines			35. MSHA Person Notified: Gerald D. Holeman		Date 06/08/2017	Time 08:20 AM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: James A. Hines				Date 06/08/2017	
38. Reason For Amendment:							