

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Electrical		3. Date/Time of Accident 07/14/2017 08:25 AM		4. Date/Time of Death 07/14/2017 09:39 AM		5. Fatal Case No 5		
6. Mine Information :										
a) Mining Company Name EP Minerals, LLC			b) Mine Name Celatom Plant			c) Parent of Mining Company EP Management Corporation				
7. Mine Location :		a) City Vale		b) County Malheur		c) State OR		8. Mine ID Number: 35-03236		9. Union: NO
10. Primary Mineral Mined: DIATOMACEOUS EARTH (DIATOMIT)			11. Number of Mine Employees:	a) Total 85	b) Underground 0	c) Open Pit/Quarry 0	d) Mill/Prep Plant 78	e) Other 7		
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total 3	b) Underground 0	c) Open Pit/Quarry 0	d) Mill/Prep Plant 2	e) Other 1			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 56		b) Contractor Employees: 3			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input checked="" type="checkbox"/> 99-Office Facility				0	0
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name Dalton J. Rodriguez					b) Age 27					
c) Regular Job Title: Grounds Keeper			d) Activity at Time of Accident: Moving Irrigation Line				<input checked="" type="checkbox"/> Mine Employee			
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total:	0 11 4		b) at the mine:	0 11 4		c) at activity (23d)	0 11 4		d) with Contractor	
25. Autopsy Performed: If Yes, Location NO						26. Mine Telephone No.: (541) 473-3285				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was moving agricultural irrigation pipe by hand and was electrocuted when the pipe came in contact with high voltage transmission lines overhead.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Not Reported			29. Model:		
30. District: M7000 Western		32. Field Office: Boise ID			33. Event Number: 6725580
34. Accident Investigator: Ronald J. Jacobsen			35. MSHA Person Notified: Ronald J. Jacobsen		Date 07/14/2017
					Time 08:55 AM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Ronald Jacobsen			Date 07/17/2017
38. Reason For Amendment:					