

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 07/27/2017 08:45 PM		4. Date/Time of Death 07/27/2017 09:31 PM		5. Fatal Case No 7							
6. Mine Information :															
a) Mining Company Name Asarco LLC, a Delaware limited liability			b) Mine Name MISSION/SAN XAVIER/EISENHOWER			c) Parent of Mining Company Grupo Mexico S A									
7. Mine Location :		a) City Sahuarita		b) County Pima		c) State AZ		8. Mine ID Number: 02-00135		9. Union: YES					
10. Primary Mineral Mined: COPPER ORE MINING, N.E.C.			11. Number of Mine Employees:		a) Total 662	b) Underground 0	c) Open Pit/Quarry 372		d) Mill/Prep Plant 287	e) Other 3					
12. Contractor Name:						13. Union		14. Contractor ID Number:							
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code							
16. Number of Contractor Employees:		a) Total	b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other						
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 251		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident									20. Mining Height:						
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches					
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility						45	0					
21. Nonfatal Injuries:			22. Fatal Injuries: 1												
23. Victim Information :															
a) Name Gabriel A. Benitez					b) Age 41										
c) Regular Job Title: Haul Truck Driver				d) Activity at Time of Accident: Utility Crew				<input checked="" type="checkbox"/> Mine Employee							
24. Experience :	Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days								
a) Total:	5	2	1	b) at the mine:	5	2	1	c) at activity (23d)	3	0	0	d) with Contractor	0	0	0
25. Autopsy Performed: If Yes, Location YES Pima County Medical Examiner Office								26. Mine Telephone No.: (520) 648-2500							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On July 27, 2017, a miner was fatally injured when his light-duty truck was run over by a haul truck. The victim was pronounced dead at the scene.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Komatsu				29. Model: 930E-4			
30. District: M6000 Rocky Mountain		32. Field Office: Mesa North AZ			33. Event Number: 6776009		
34. Accident Investigator: Lee Hughes				35. MSHA Person Notified: Peter A. Del Duca		Date 07/27/2017	Time 11:00 PM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Peter A. Del Duca				Date 07/28/2017	
38. Reason For Amendment:							