

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4120384
 Company Name Performance Coal Company
 Mine Name Upper Big Branch
 Mine I.D. Number 46-08476
 Date(s) of Mine File Review 6-19-2008
 D Status Y Citation/Order No. 7279743 3-7-08
 Dates of Inspection: began 6-19 completed 6-19
 Pre-Inspection Conference Date 6-19-2008
 Company Representative(s) Rick Hodge
Superintendent
 Miners Representative(s) None
 Post-Inspection Conference Date 6-19-2008
 Company Representative(s) Rick Hodge
Superintendent
 Miners Representative(s) None
 Comments:
 Inspector's Initials [Redacted] Supervisor's Initials and Date RR 6-20-08

DAILY COVER SHEET

Date 6-19-08 Event No. 4120784
 Arrived at the Mine 7:00 Departed from the Mine 14:30
 List Records Books Checked Pre-shift & On-shift
#1 and #2 section
 Accompanied By: Company Representative Bill Harless
Mine Foreman
 Miners Representative None

AREAS OF INSPECTION ACTIVITY:

Faces 1-7 on #1 Section
Track

Inspector's Initials [Redacted]
 Supervisor's Initials and Date RR 6-20-08 Page No. 2


Date 6-19-08
Left H. 18,620
Night H. 16,530
#1 Section
LOB 15,720
#2 Section

Inspector's Initials [Redacted]
 Supervisor's Initials and Date RR 6-20-08 Page No. 2

Date 6-19-08

I spoke with Bill Harless and Rick Hodge about doing a methane spot inspection. I checked the Prestige + Onshipe for #1 and #2 sections. Rode the track from the outside to the #1 section. No methane was found while on the track.

Went across the faces #1-7 no CH₄ was found on the #1 section. Rock dust in the air and roof appeared OK. The bottom is

Inspector's Initials Supervisor's Initials and Date RR6-20-08 Page No. 3Date 6-19-08

is breaking up pretty bad. I watch the miner loaded 5-6 shuttle cars. I traveled the track to the surface. No CH₄ was found while traveling the track 0² 20.89% in the mine. I had a closeout with Rick Hodge. ~~RR6~~ Talk about my findings.

Inspector's Initials Supervisor's Initials and Date RR6-20-08 Page No. 4